



SSX32 PWR
1 Main Power In +5 to 12v
2 +3.3v regulated output
3 Ground

BANK1 PWR
1 SSX32 PWR Jump 1&2 to supply power to servos from main power input.
2 Bank 1 Power Input
3 Ground

BANK2 PWR
1 SSX32 PWR Jump 1&2 to supply power to servos from main power input.
2 Bank 1 Power Input
3 Ground

SIN
1 Serial input
2 +3.3v regulated output
3 Ground

SOUT
1 Serial output
2 +3.3v regulated output
3 Ground